

MAKE: LADA

TYPE: Niva

MODEL: 2121




YEAR: 1978 on




DETAIL:



LADA-51

LADA

FRONT	QTY	PART NUMBER
<p>COIL SPRING</p>  <p>Linear Rate Raised Height (35mm Lift)</p>	1	<p>Price Code </p> <p>C33-002 (B)</p>
<p>SHOCK ABSORBER</p>  <p>Heavy Duty Twin Tube Gas</p>	2	<p>GS33-087B</p> <p style="color: red; font-size: small;">Front lower shock mount requires strengthening</p>

REAR	QTY	PART NUMBER
<p>COIL SPRING</p>  <p>Linear Rate Raised Height (35mm Lift)</p>	1	<p>Price Code </p> <p>C33-003 (B)</p>
<p>SHOCK ABSORBER</p>  <p>Heavy Duty Twin Tube Gas</p>	2	<p>GS33-635W</p>

Torsion Bars: Sold in Pairs
Coil Springs: Sold in Pairs, (A) (B) (C) etc... Indicates Price Code